

Facility Summary in MUSSELSHELL County in the City of MELSTONE

Owner: Jakes Garage Inc		Address: 221 US Highway 12, Melstone, MT 59054	
Sys Fac ID 3301481	FITS SITE 40339	Location Name JAKES GARAGE	Location Street Address 221 US HIGHWAY 12
		Location City MELSTONE, MT 59054	Location Phone (406) 358-2389
Operating Permit Renewal Date: 30-Mar-2010		Last inspected on: 03-Oct-2006	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
8 / 08 Currently In Use	3770	12/1/1998 08 / No	Gasoline 3,750	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>(B) (D) E F G H I J K L</div> </div>	Yes Yes Yes
9 / 09 Currently In Use	3771	12/1/1998 08 / No	Gasoline 2,250	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F G H I J K L</div> <div>(B) (D) E F G H I J K L</div> </div>	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in MUSSELSHELL County in the City of ROUNDUP

Owner: McCleary Distributing Inc			Address: PO Box 406, Roundup, MT 59072-0406		
Sys Fac ID 3301083	FITS SITE 40336	Location Name MAIN STREET TEXACO	Location Street Address 304 MAIN ST	Location City ROUNDUP, MT 59072	Location Phone (406) 323-3646
Operating Permit Renewal Date: 29-Sep-2007			Last inspected on: 23-Sep-2004		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
7 / 07 Temporarily Out of Use	1588	11/20/1990 16 / No	Gasoline 3,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> A B C D E F G H I J K L ● ● E F G H I J K L </div>	Yes Yes Yes
8 / 08 Temporarily Out of Use	1589	11/20/1990 16 / No	Gasoline 3,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> A B C D E F G H I J K L ● ● E F G H I J K L </div>	Yes Yes Yes
9 / 09 Temporarily Out of Use	1590	11/20/1990 16 / No	Gasoline 3,000	STI-P3 None	Fiberglass Reinforced Plas None	Pressurized	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> A B C D E F G H I J K L ● ● E F G H I J K L </div>	Yes Yes Yes

Owner: Wells Fargo Bank Roundup			Address: 12 Main St, Roundup, MT 59072-2828		
Sys Fac ID 3302079	FITS SITE 40351	Location Name WELLS FARGO BANK ROUNDUP	Location Street Address 12 MAIN ST	Location City ROUNDUP, MT 59072	Location Phone (406) 323-2000
Operating Permit Renewal Date: 28-Dec-2007			Last inspected on: 06-Oct-2004		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / S2 Currently in Use	3495	10/6/1993 13 / No	Heating Oil 2,000	STI-P3 Double-Walled	Copper Double-Walled/Non-Corrod	Safe Suction	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> A B C D E F G H I J K L B D E F G H I ● K L </div>	Yes Yes Yes

Owner: McCleary Distributing Inc			Address: PO Box 406, Roundup, MT 59072-0406		
Sys Fac ID 3305030	FITS SITE 40390	Location Name CONOCO CONVENIENCE CENTER	Location Street Address 806 MAIN ST	Location City ROUNDUP, MT 59072	Location Phone (406) 323-1108
Operating Permit Renewal Date: 14-Dec-2007			Last inspected on: 23-Sep-2004		

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	Installed Spill/Over/CPMe
1 / 09 Currently in Use	1594	10/1/1996 10 / No	Diesel 4,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<div style="display: flex; justify-content: space-between; font-size: 0.8em;"> A B C D E F G H I J K L B D E F ● H I J K L </div>	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Facility Summary in MUSSELSHELL County in the City of ROUNDUP

2 / 07	1592	8/30/1989	Gasoline	STI-P3	Flexible Plastic	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use		17 / No	4,000	None	Double-Walled		● ● E F G H I J K L			
3 / 08	1593	9/1/1992	Gasoline	STI-P3	Flexible Plastic	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use		14 / No	4,000	None	Double-Walled		● ● E F G H I J K L			
4 / 06	1591	8/30/1989	Gasoline	STI-P3	Flexible Plastic	Pressurized	A B C ● E F G H I J K L	Yes	Yes	Yes
Currently in Use		17 / No	4,000	None	Double-Walled		● ● E F G H I J K L			
10 / 10	1595	10/1/1996	Diesel	STI-P3	Flexible Plastic	Pressurized	A B C D E F ● H I J K L	Yes	Yes	Yes
Currently in Use		10 / No	2,000	Double-Walled	Double-Walled		B D E F ● H I J K L			
11 / 11	1596	10/1/1996	Diesel	STI-P3	Flexible Plastic	Pressurized	A B C D E F ● H I J K L	Yes	Yes	Yes
Currently in Use		10 / No	4,000	Double-Walled	Double-Walled		B D E F ● H I J K L			
12 / 12	1597	10/1/1996	Diesel	STI-P3	Flexible Plastic	Pressurized	A B C D E F ● H I J K L	Yes	Yes	Yes
Currently in Use		10 / No	2,000	Double-Walled	Double-Walled		B D E F ● H I J K L			

Owner: Stockton Oil Co Billings

Address: PO Box 1756, Billings, MT 59103-1756

Sys Fac ID	FITS SITE	Location Name	Location Street Address	Location City	Location Phone
3306612	40407	EXPRESS CENTER CONVENIENCE STORE	701 1ST AVE W	ROUNDUP, MT 59072	(406) 323-1171
Operating Permit Renewal Date:		07-Feb-2009	Last inspected on:		07-Nov-2005

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	Installed
Status				Secondary Option	Secondary Option		Piping Release Detection	Spill/Over/CPMe
1 / 01	3757	3/26/1985	Gasoline	Cathodically Protected Steel	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes
Currently in Use		22 / No	10,000	Lined Interior/Impressed Curre	None		● ● E F G H I J K L	
2 / 02	3758	3/26/1985	Gasoline	Cathodically Protected Steel	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes
Currently in Use		22 / No	8,000	Lined Interior/Impressed Curre	None		● ● E F G H I J K L	
3 / 03	3759	3/26/1985	Gasoline	Cathodically Protected Steel	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes
Currently in Use		22 / No	4,000	Lined Interior/Impressed Curre	None		● ● E F G H I J K L	
4 / 04	1985	10/1/1998	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes
Currently In Use		08 / No	8,000	Double-Walled	Double-Walled		B D E F ● H I J K L	
5 / 05	1986	10/1/1998	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes
Currently In Use		08 / No	5,000	Double-Walled	Double-Walled		B D E F ● H I J K L	
6 / 06	1987	10/1/1998	Diesel	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plas	Pressurized	A B C ● E F G H I J K L	Yes
Currently In Use		08 / No	4,000	Double-Walled	Double-Walled		B D E F ● H I J K L	

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed